
FUSE
PTCSMD
USBSMD
USB
FT232RL
Pressure Sensor
GYRO-Z
ADC
Relay
Expansion Ports
SPI
Telem Port
Pitot
Black Box
DF
SW1
I2C Traslator
Accel
12uF Cap
Dual 3.3V Reg
Volt Dividers
DOWN=LOW
ADXL335
CRP-04113
EM406
I2C Port
NO GPS!
SW2
ON
BLUE
GREEN
YELLOW
RED
RANGE
TX
RX
A
B
C